

ANNUAL SURVEYS.

6878

No. 764 Survey held at London Date Nov 13 1840
 on the ship Esperates Master Loumay
 Tonnage 617 Built at Liverpool When built 1834
 By whom built _____ Owners Samison & Co
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Underway Dock

[Handwritten Signature]

Original Survey, No. 92, Port of Liverpool 1837 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treonails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Two keels of tin keel copper has been rubbed off
 as required by the Instructions. but the ship does not to have sustained the
lightest injury in other respects - The copper is smooth
and the copper should remain as directed R A 1

Committee Minute 9th Nov 1840
 Character assigned 12 A 1 *[Signature]*

No. _____ Survey held at London Date Nov 14 1840
 on the Boat Thomas Joseph Pitt Master Cole
 Tonnage _____ Built at London When built 1840
 By whom built Anderson Owners Thomas Cooper
 Port belonging to London Destined Voyage Cape Good Hope
 If Surveyed Afloat or in Dry Dock Underway in Dock at Dock

Original Survey, No. _____ Port of London 1840 Classed _____

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treonails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Keels from keel up on the and
 as required by the Instructions. coppering on paper to 1/2 inch

Committee Minute 1840
 Character assigned See Sld No 1843 *[Signature]*



© 2019
 Lloyd's Register
 Foundation