

ANNUAL SURVEYS.

Change of Property

6957

No. Survey held at London Date Nov 25th 1840
 on the B^k Conservative Master R. A. Cousins
 Tonnage 651 1/2 M Built at Sunderland When built 1840
 By whom built J^r Gales & Son Owners R. Green & Son X
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock King's Dock

Original Survey, No. 1791 Port of Sunderland 1840 Classed 10 B

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchora No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>1840</u>

General Observations and Opinion,
 as required by the Instructions,

*Copper to 13 ft on Paper appears to be a few and
 Substantial Vapors. Bottom has been holed
 and caulked at the present time.*

Committee Minute 1st Decr 1840

Character assigned

10 A 1 George Bayley

Change of Property

No. 40 Survey held at London Date Nov 26th 1840
 on the B^k Harcourt Master John Coleman
 Tonnage 324 1/2 M Built at America When built
 By whom built Owners W. Clark John X
 Port belonging to London Destined Voyage South Sea
 If Surveyed Afloat or in Dry Dock Batchellors Quay

Original Survey, No. 3315 Port of London 1837 Classed A. Expended

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchora No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>1840</u>

General Observations and Opinion,
 as required by the Instructions,

*Remains Wood, Sheathing & Caulked S. Copper to 13 ft
 Sides & Sides of Rig to 13 ft & 13 ft
 This vessel presents a fine appearance from the
 fastenings & waterway down. Dec 1 1840*

Committee Minute 1st Decr 1840

Character assigned

10 A 1 George Bayley