

Coffin
0903

REPORT of SURVEY for REPAIRS.

No. 160 Survey held at London Date June 21 1840
 on the Brig Abigail Master Amman
 Tonnage 174 Built at Shoreham When built 1834 April
 By whom built J. B. Ballew Owners W. H. Hutton
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Shoreham Dock

Original Survey, No. 3221 Dated 1837 Classed 11 A 1
 Port London

Repairs

*Stopped cables but up and unspliced
 as before - Rigging all down and
 re-shantling*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Top-sides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <i>Good and efficient</i>
Plank Shears	Counter	Sails
Waterways	Plank & Treennils (Outside to the Water's Edge)	Cables
Hatchway Coverings	Rudder	Anchors No. of
Breasthooks	Copper <u>1840</u>	Standing & Running Rigging <i>Substantial</i>

General Observations and Opinion,
 as required by the Instructions.

*In my opinion the Ship is eligible to remain
 as classed 11 A 1*



© 2019 Lloyd's Register

The Amount of Fee.....£ : is received by me,

Committee's Minute 1st Oct 1840

Character assigned 11 A 1

Lloyd's Register
 Foundation