

ANNUAL SURVEYS.

7013

No. 303 on the Ship Boyne Survey held at London Date Nov 25th 1840
 Tonnage 632 Built at Cardiff Master Mitchell
 By whom built James Owners James
 Port belonging to London Destined Voyage London & America
 Surveyed 11/25 in Dry Dock Sup: Cowling & Young

Original Survey, No. 4322 Port of London

Classed * A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Copstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Soils
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions, At the present time, shipped off the copper, painted the bottom & sheathing with yellow metal. The ship is in very good condition and may remain as classed.

Committee Minute 14th Dec 1840

Character assigned 11/25 At the present time, shipped off the copper, painted the bottom & sheathing with yellow metal. The ship is in very good condition and may remain as classed.

No. 523 on the Ship Chopatra Survey held at London Date Nov 25th 1840
 Tonnage 231 Built at Swansea Master Keshnole
 By whom built James Owners James
 Port belonging to London Destined Voyage London & America
 Surveyed 11/25 in Dry Dock Sup: Cowling & Young

Original Survey, No. 860 Port of Swansea, London 30/11/51

Classed 11 A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Copstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Soils
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions, At the present time, repaired the copper & painted the bottom & sheathing with yellow metal. The ship is in a very good condition and may remain as classed.

Committee Minute 14th Dec 1840

Character assigned 11/25 At the present time, repaired the copper & painted the bottom & sheathing with yellow metal. The ship is in a very good condition and may remain as classed.