

ANNUAL SURVEYS.

7365

No. 657 Survey held at London Date 24 March 1841
 on the "M. England" Master Lewis
 Tonnage 1125 Built at Chipperton When built 1814
 By whom built — Owners J Ward
 Port belonging to London Destined Voyage —
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 3083, 4680, Port of London
1576

Classed F, 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings <u>good</u>	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails <u>Sufficient</u>
Plank Shears	Wales <u>good</u>	Cables <u>und</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of <u>good</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,

as required by the Instructions,

The fore and main lengths of plank shears stowed
also spirkettling, the run has been foreward and good
and sound continues in good and efficient condition
and may remain as classed

Committee Minute 26th March 1841

Character assigned F, 1

No. 269 Survey held at London Date 24 March 1841
 on the "M. William Harrington" Master A. Inch
 Tonnage 340 Built at New Brunswick When built 1826
 By whom built — Owners Nichol
 Port belonging to Newcastle Destined Voyage Indies Muramachi
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 345, 540, Port of Newcastle
1557

Classed F, 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,

as required by the Instructions,

The lower deck fastenings are not
firm and the ship is generally out of position
and not been opened above the bulwarks, and is

Committee Minute 26th March 1841

Character assigned Upper Character

Input not opened