

# ANNUAL SURVEYS.

No. 328 Survey held at London Date 7 April 1841  
 on the My Charlotte Wyllie Master Walker  
 Tonnage 150 Built at Poole When built 1821  
 By whom built — Owners Kutling  
 Port belonging to London Destined Voyage Africa  
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 2368, 2307 Port of London  
3625, 4070, 4705, 6738,

Classed A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,

as required by the Instructions,

Is in good and efficient Condition for  
the conveyance of dry and perishable cargoes and may be  
continued as classed

Committee Minute 23rd April 1841

Character assigned A.1

No. 28 Survey held at London Date 7 April 1841  
 on the Hilbain Bk Master Shaw  
 Tonnage 419 Built at Greenock When built 1839  
 By whom built — Owners Walker  
 Port belonging to Greenock Destined Voyage —  
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 787 Port of Clyde

Classed A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,

as required by the Instructions,

Is a well built ship and in good and  
efficient Condition and may be continued as classed

Committee Minute 23rd April 1841

Character assigned A.1



© 2019

Lloyd's Register  
Foundation