

REPORT of SURVEY for REPAIRS.

& Change of Owners

No. 374 Survey held at London Date May 24 1847
 on the Bg Alfred Master Mason
 Tonnage 135 Built at Alton When built 1819
 By whom built _____ Owners Crozier
 Port belonging to London Destined Voyage Liberator
 If Surveyed Afloat or in Dry Dock in the London Dock

Original Survey, No. 1030, 2334, Dated 1839 Classed A, 1
3326, 5658,
 Port London

REPAIRS *In February last at Fernandoz Po, new stbd Waterway, Plank Shear, & three new stakes in the Deck on each side. At the present time caulked, new planks in the Topsides in the way of the Chain plate bolts*

Also at Fernandoz Po two new deck beams & several new bolging knees

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *The timber where exposed in good condition and I am of opinion she may remain as Classed A, 1*

W. Middleton

The Amount of Fee.....£ : 10 : is received by me, *[Signature]*

Committee's Minute 1st June 1844

Character assigned A, 1 *under repair*



© 2019

Lloyd's Register
Foundation

LON 610 - 0303