

REPORT of SURVEY for REPAIRS.

No. 26 Survey held at London Date June 13th to July 12 1841
 on the 1st Hunt Master Miller
 Tonnage 372 Built at Dover When built 1803
 By whom built _____ Owners H. Bennett & Co.
 Port belonging to London Destined Voyage South Sea Fishery
 If Surveyed Afloat or in Dry Dock Lincolne Dock

Original Survey, No. 2615, 2656 Dated 1837 Classed A. 1
 Port London

REPAIRS At the present time New Topsides, Sheer & Blackstrokes of Caulking
 for excepting about 1/3 of the Topside on the Starboard side which was
 shifted in 1837. A number of Septembers shifted with sound
 secondhand Locust and Red Cedar about 1/4 of the
 board sheathing new at the present time. The whole of
 the in and out bolts to the upper Deck fastenings shifted
 Caulked from the keel up and generally overhauled
 Copper to the wale

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Scals
Waterways	Plank & Treennails	Cables
Hatchway Comings	(Outside to the Water's Edge)	Anchors No. of
Breasthooks	Rudder	Standing & Running Rigging
	Copper	

General Observations and Opinion. The Hull of this vessel is now in good and efficient
 condition for remaining as classed B.

Spent not yet outboard

The Amount of Fee. £ 2 : - - is received by me,

Committee's Minute 23rd July 1841

Character assigned 1st