

# REPORT of SURVEY for REPAIRS.

No. 58 Survey held at London Date August 18<sup>th</sup> 1841  
 on the Barque Pontaloon Master Canadian  
 Tonnage 252 Built at Yarmouth When built 1838  
 By whom built \_\_\_\_\_ Owners J. A. Howard  
 Port belonging to Yarmouth Destined Voyage Transit  
 If Surveyed Afloat or in Dry Dock Crisps ways

Original Survey, No. 220 Dated \_\_\_\_\_ Classed 12 A1

Port Yarmouth, Nuc. 804, Lon. 5410, Yaw. 393,

## REPAIRS

*At the present time Caulked the  
 Waterway seam and timber heads -*

## Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Cupstn
Lower Deck Beams & Fastenings	Topside	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Coverings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

## General Observations and Opinion.

*This vessel is in a most efficient state for  
 for the safe conveyance of any perishable goods to  
 and from all ports of the world in my opinion  
 should remain as classed*

The Amount of Fee.....£ ..... is received by me,

Committee's Minute 20th August 1841

Character assigned 12 A1

Special Report Condition 12 A1

*all 11/11/41*

Lloyd's Register  
 Foundation

10N611-0124