

REPORT of SURVEY for REPAIRS.

1832
1807

7865

No. 101 Survey held at London Date August 17th 1841
 in the B^e Eclipse Master W^m Bennett
 Tonnage 291 Built at Poole When built 1807
 By whom built W^m Bennett Owners W^m Bennett
 Port belonging to London Destined Voyage South Sea Voyaging
 Surveyed Afloat or in Dry Dock Swanwick Dock

Original Survey, No. Dated Not Classed

Port

REPAIRS At the present time - Stoppers - 4 Strakes of the upper course on each side - and 4 Strakes inside at the same height, all the Buttocks Plank on the Larboard Side, one plank on Starboard Buttocks - 2 Half Transoms - Upper piece of main part of Knight Heads 2 Breast Hooks - 6 Upper Deck Beams & one half beam, shifted - 54 Filling Timbers - recocked and new Span Long Riggers - New Kall Bitts - Carriek Bitts and Upper Deck Wood refitted several planks in Topside Shifts Bottom recocked - and the Hull throng, recocked - Bottom Bitts. Wood shifted & recocked -

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan <u>up till 1841</u>
Lower Deck Beams & Fastenings	Topside	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treonails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchor No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,

This vessel is now in an efficient state for her intended voyage. In my opinion is eligible to be classed.

The Amount of Fee.....£ 2 : - : - is received by me,

Committee's Minute 18

Character assigned F. 1

© 2019

Lloyd's Register Foundation

LON611-0152