

# ANNUAL SURVEYS.

1942

No. <sup>1022</sup> 1022 Survey held at London Date 13 Sept 1841  
on the 1st Brandy Master Roxes  
Tonnage 144 Built at Littlehampton When built 1841  
By whom built 144 Owners Wm & Co  
Port belonging to London Destined Voyage Rotterdam  
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 174 Port of Portsmouth

Classed A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>Good</u>
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging <u>new</u>
	Windlass	Copper

General Observations and Opinion,  
as required by the Instructions,

The Standing Rigging was found of so bad quality as to be unfit for service has now been replaced with new & may remain as

Committee Minute 21st Septe 1841

Character assigned 12 D 1

clipped  
Hunting

No. <sup>107</sup> 107 Survey held at London Date 14 Sept 1841  
on the Arthur Master Kachum  
Tonnage 119 Built at Shan When built 1832  
By whom built 119 Owners Kachum  
Port belonging to Bombay Destined Voyage Bitter  
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 448 Port of Quindoo

Classed A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>Good</u>
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,  
as required by the Instructions,

Some planks shifted in the Deck is in good and efficient condition and may remain as clipped

Committee Minute 21st Septe 1841

Character assigned 12 D 1

© 2019  
Lloyd's Register  
Foundation