

REPORT of SURVEY for REPAIRS.

8205
A

No. 85 Survey held at London Date Sep 27 & Oct 27 1841
 on the Barque Parrock Hall Master Parsons
 Tonnage 345 Built at Yarmouth When built 1837
 By whom built _____ Owners Somers
 Port belonging to London Destined Voyage C
 If Surveyed Afloat Y in Dry Dock Yes & Commercial docks

Original Survey, No. 173 Dated _____ Classed 12 A 1
 Port Yarmouth, London 3/5, 5891.

REPAIRS

At the present time took out & fitted a new
 Hemson; fitted two new ruffler stantions, repaired
 Rails & bulworks, shipped caulked the bottom
 & Sheathed with Yellow Metal.

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

Handwritten notes in brackets:
 { good } (for Decks)
 { good when seen } (for Transoms)
 { good } (for Counter)
 { good & efficient } (for Masts, Yards, &c.)
 { Yellow Metal } (for Copper)

General Observations and Opinion,

This Ship is in a very good & efficient state
 fit for the safe conveyance of any & perishable goods
 to & from all parts of the world & in my opinion
 should remain as classed

The Amount of Fee, £ _____ is received by me,

Committee's Minute 7th December 1841

Character assigned 12 A 1 renewed

Signature: Nathl. J. Clark

Signature

Signature



© 2019

Lloyd's Register
 Foundation

LON 612-0025