

REPORT of SURVEY for REPAIRS.

8245

Damage

No. Survey held at London Date Nov-30, Dec-10 1841
 of the Schooner Pt Master Buckley
 Tonnage 117 Built at Spewick When built 1835
 by whom built Owners Stow & Co
 Port belonging to London Destined Voyage Myrina
 of Surveyed Afloat or in Dry Dock Stow's ways

Original Survey, No. 117 Dated Classed 11 A1

Port Spewick, London 2362 Liverpool 2306, 3466 & 4126

REPAIRS

At the present time fitted a new chain plate;
 rebolter the shelf. fitted 2 pair of Iron knees.
 abreast the main mast. Caulked from the
 Copper up, timber heads & waterways. Repaired
 Bulwarks & Rails - & repainted Rudder pintles
 two lower masts. Rigging overhauled.

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame <u>good when seen</u>	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>good and</u>
Plank Shears	Counter <u>good</u>	Sails <u>sufficient</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,

This vessel is in a very efficient state fit for the
 safe conveyance of dry & perishable cargoes to and from
 all parts of the world & in our opinion should remain
 as classed

The Amount of Fee.....£ : is received by me,

Committee's Minute 24th December 1841

Character assigned 11 A1

Received 10. 4

*Wm. Jones
 20 Dec
 Lloyd's Register*



Lloyd's Register
 Foundation

L00612-0067