

ANNUAL SURVEYS.

8379

No. 20 Survey held at London Date Jan 11th 1842
 on the Steam Vessel Caledonia Master Chesman
 Tonnage 425 Built at London When built 1836
 By whom built Green & Wigram Owners G. S. & Co.
 Port belonging to London Destined Voyage Lombard
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 2542, 7/11/44, Port of London Jan 1. 1841 Classed NA1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper <u>1842</u>

General Observations and Opinion, This vessel was docked on the 14th & left the dock on the 15th
 as required by the Instructions, was not seen by me in Dock - Reported to have been stripped
caulked from the keel up - part new false keel - & recoppered
to 11 feet. The holding down bolts were not particularly examined
His reports to have been in good condition and caulked soundly
 Committee Minute 1st February 1842 of which there is no reason to entertain any
 Character assigned Rec'd & App'd doubt. The present report to make for the
purpose of recording the foregoing
George Bayley

No. 180 Survey held at London Date Jan 29th 1842
 on the B^k Jane Catharine Master Blake
 Tonnage 350 Built at Bristol When built 1824
 By whom built Owners Cannon
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Unlikely Dry Dock

Original Survey, No. 412, 3214, Port of London 1842 Classed Restored NA1
3084, 4335, 4825, 6169, 7357, 8326 Jan 1839

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, The four planks of the stem strakes referred to in
 as required by the Instructions, former report, are now removed, in course of replacing
with new - She has now in all respects complied with
the rule for Restoration to entitle her to commence
 Committee Minute 1st February 1842 with the present year 1842
 Character assigned Rec'd & App'd 1st Jan 1842. George Bayley
George Bayley