

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 859 Survey held at London Date Feb'y 20th 1842
 on the Bk. Apolline Master Thomas
 Tonnage 440 Built at Sunderland When built 1837
 By whom built _____ Owners Brays & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock West India Dock

Sunderland Cog,
 Original Survey, No. 3281, 3811, Dated _____ Classed 11 A 1
4318, 6306, 8315,
 Port of London

REPAIRS

Present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Sound & true</u>	Capstan <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Pumps <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Sails <u>Well found</u>
Waterways <u>"</u>	Plank and Treennails <u>Good</u> (Outside to the Water's Edge)	Cables <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Anchors No. of <u>"</u>
Breasthooks <u>"</u>	Copper <u>1040</u>	Standing & Running Rigging <u>Good</u>

General Observations and Opinion, I am of opinion she may continue as before

The Amount of Fee.....£ 200 is received by me, R

Committee's Minute 15th March 1842

Character assigned 11 A 1



© 2019

Lloyd's Register
Foundation

LON 612-0312