

8911

REPORT of SURVEY for REPAIRS.

Damage

No. 323 Survey held at London Date July 8th 1842
 on the Ship Plantaganet Master Daniels
 Tonnage 657 Built at Newcastle When built 1838
 By whom built Robt Smith & Co Owners Smith & Co
 Port belonging to London Destined Voyage India
 Surveyed Afloat in Dry Dock Miss. Hatcher & E. J. Lamb

Original Survey, No. 830 Dated _____ Classed 12 A 5

Port Newcastle Lon 520, 5266, 7721.
 REPAIRS At the present time. Shipped. Painted from
Rue over ale + Waterway beam; Sheathed with
Yellow Metal, on Paper - Repaired main channel
New bowsprit & Lower Rigging (main beam)

Decks <u>very good</u>	Transoms <u>good when seen</u>	Winlass
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good</u>	Copstan <u>good</u>
Lower Deck Beams & Fastenings <u>good</u>	Top-sides <u>good</u>	Pumps
Spirkutting <u>good</u>	Wales <u>"</u>	Masts, Yards, &c. <u>New braced main yard</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Sails
Waterways <u>"</u>	Plank and Trewnails (Outside to the Water's Edge) <u>"</u>	Cables <u>good and well fished</u>
Hatchway Coverings <u>"</u>	Rudder <u>"</u>	Anchors No. of <u>1</u>
Breasthooks <u>good</u>	Copper <u>Y Metal New</u>	Standing & Running Rigging <u>New</u>

General Observations and Opinion This ship is in a very high state of efficiency and on completion should remain as Classed 12 A 5

The Amount of Fee £ _____ is received by me _____
 Committee's Minute 15 July 1842
 Character assigned 12 A 5

