

REPORT OF SURVEY for REPAIRS.

8993

No. Survey held at LONDON Date July 5 1842
 on the Scourist Ann Master Gillbank
 Tonnage 236 Built at Perth When built 1821
 By whom built Owners J. & A. Company
 Port belonging to LONDON Destined Voyage
 If Surveyed Afloat or in Dry Dock Septford creek
E. & C. 36 p. 118 T. R.

Original Survey, No. 1542, 253 Dated Classed By
Ship architect

Port LONDON

REPAIRS At the present time:
Caulked from the Copper over all; Repaired
the Deck about 1/2 new, one New Beam & Stow.
new fore mast, and a general overhaul in
the Sails Engines & Boilers.

Present Condition of the			
Decks <u>Upper & Good</u>	Transoms <u>Good where seen</u>	Windlass <u>Good</u>	
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u> </u>	Capstan <u>"</u>	
Lower Deck Beams & Fastenings <u> </u>	Top-sides <u>Good</u>	Pumps <u>"</u>	
Spirketting <u> </u>	Wales <u>"</u>	Masts, Yards, &c. <u>new for base</u>	
Plank Shears <u>good</u>	Counter <u>"</u>	Sails <u> </u>	
Waterways <u>"</u>	Plank & Treennails <u>"</u>	Cables <u>hale for use</u>	
Hatchway Comings <u>"</u>	(Outside to the Water's Edge)	Anchors No. of <u> </u>	
Breasthooks <u>firm</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>	
	Copper <u> </u>		

General Observations and Opinion, This vessel is in a firm and apparently
sound state in our opinion fit to carry
any perishable goods and should be classed
Ex. 1

The Amount of Fee.....£ 1 : - is received by me,

Committee's Minute 12th August 1842

Character assigned

© 2019 Lloyd's Register Foundation