

REPORT of SURVEY for REPAIRS.

Change of property

No. 9469 Survey held at London Date Jan 28th 1842
 on the Ship City of Norwich Master Bird
 Tonnage 557 Built at Cochin When built 1838 March
 By whom built _____ Owners R Green
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackwall

Original Survey, No. _____ Dated Sept 1840 Classed 12 A 1

Port Liverpool

REPAIRS Copper largely repaired. Caulked from Copper
to Watertight Seam

Present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Not seen</u>	Capstan <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Pumps <u>Good</u>
Spirkettling <u>Good</u>	Wales <u>Good</u>	Masts, Yards, &c. <u>Overhauling</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Overhauling</u>
Waterways <u>Good</u>	Plank and Treenails (Outside to the Water's Edge) <u>Good</u>	Cables <u>Efficient</u>
Hatchway Comings <u>Good</u>	Rudder <u>Good</u>	Anchors No. of <u>3. 1. 1</u>
Breasthooks <u>Good</u>	Copper <u>up 1842</u>	Standing & Running Rigging <u>Well down & overhauling</u>

General Observations and Opinion, This ship throughout presents a remarkably
firm appearance upon her fastenings &c in my
opinion entitled to remain as classed 12 A 1

George Bayley

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18 _____

Character assigned _____



© 2019

Lloyd's Register
 Foundation
 LON 614-0127