

REPORT of SURVEY for REPAIRS.

Change of property

9493

No. 14 Survey held at London Date Feb 21 1843
 on the St. Madras Master Kitching
 Tonnage 331 Built at Whitehaven When built 1827
 By whom built _____ Owners Capt. H.
 Port belonging to London Destined Voyage Swan River
 If Surveyed Afloat or in Dry Dock Green Dock

Original Survey, No. 4457, 4207, 5497, 7788, Dated August 1841 Classed 10 A. 1
 Port London

REPAIRS

At the present time on clearing away the keel the midship part of the keelson was discovered to be defective - This has been shifted and a new Riding Keelson fitted in a good and efficient manner - The ship being well secured to the beams

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,

She is now in my opinion fit for the conveyance of dry and perishable cargoes to and from all parts of the world, and eligible to be classed A. 1

The Amount of Fee.....£ 2 : - : - is received by me,

Committee's Minute 24th February 1843

Character assigned A. 1



Lloyd's Register
Foundation

10464-0153