

9105

# REPORT of SURVEY for REPAIRS.

No. 3 Survey held at London Date Jan 4 & Feb 4 5th 1847  
on the M "Bachelor" Master Murray  
Tonnage 341 Built at Brunswick When built 1827  
By whom built - Owners Lucretia  
Port belonging to London Destined Voyage -  
If Surveyed Afloat or in Dry Dock Am Dr afloat

Original Survey, No. 114 Dated - Classed Fil SS. 40-5th

Port Liverpool, Lon 2268, Gr 290.

REPAIRS. At the present time, greater part new Sheer Strakes and some new plank in the Topsides New bolts to upper deck knees and caulked

Present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>Good when seen</u>	Capstan <u>-</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Pumps <u>do</u>
Stirking <u>Good</u>	Wales <u>do</u>	Masts, Yards, &c. <u>do</u>
Rank Shears <u>do</u>	Counter <u>do</u>	Sails <u>2 sails</u>
Waterways <u>do</u>	Plank & Treenails (Outside to the Water's Edge) <u>do</u>	Cables <u>Sufficient Good</u>
Stitchway Comings <u>do</u>	Rudder <u>do</u>	Anchors No. of <u>do</u> <u>do</u>
Keelhooks <u>do</u>	Copper <u>-</u>	Standing & Running Rigging <u>do</u> <u>do</u>

General Observations and Opinion, The bottom was exposed in performing the above repairs proved remarkably good and she is now in an efficient condition for the conveyance of dry and perishable cargoes and may remain as classed

The Amount of Fee.....£ 2 : - : - is received by me, HH

Committee's Minute 21st October 1842

Character assigned Fil

Record Repairs LL

Continued  
Wm. J. Clark



© 2019  
Lloyd's Register  
Foundation  
LON 614 0242