

ANNUAL SURVEYS.

9199

No. 103 Survey held at London Date Oct 31 184 2
 on the Bk Commodore Master B. Hore
 Tonnage 203 Built at Newport When built 1833
 By whom built _____ Owners Smith & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Dry Dock

Liverpool 1020,
 Original Survey, No. 4440, 5346 Port of London
6767, 8013, 8731,

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, Bottom examined and is in all respects in an efficient
 as required by the Instructions, state to retain her present Class

Committee Minute 4th November 184 2

Character assigned 12 A 1

No. 15 Survey held at London Date Nov 1 184 2
 on the Schooner Gateway Sloop Master J. Pottle
 Tonnage 220 Built at Sunderland When built 1839
 By whom built _____ Owners Gilby & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Crisps Mays

Original Survey, No. 4564 Port of Liverpool

Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, Bottom examined & is in very good condition & retain her
 as required by the Instructions, present character Sanctified from the Yellow Metal up

Committee Minute 4th November 184 2

Character assigned 10 A 1



© 2019

Lloyd's Register
Foundation

104614-0277