

9670
S.

If Sur
22

8

Original

REPAIRS

in the frame

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettig	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, In our opinion this ship is fit for the conveyance of dry and perishable cargoes to and from all parts of the world & eligible to remain as classed 1st F.

The Amount of Fee.....£ 3 : — is received by me, *as above*

Committee's Minute 20 April 1843

Committee's Minute 20 April 1848
Character assigned A. I. I. Cooper

Special \$44.00

George Bayley
Peter Martinay

LON 615-0110