

# ANNUAL SURVEYS.

9/32

No. 295 Survey held at London Date May 5<sup>th</sup> 1843  
 on the By Munoz Master Flight  
 Tonnage 154 Built at Funchal When built 1839  
 By whom built \_\_\_\_\_ Owners Forster & Co  
 Port belonging to London Destined Voyage Urica  
 If Surveyed Afloat or in Dry Dock Smiths Ways

Original Survey, No. 1457, Port of London Classed 11A1  
9150, 9725

The Surveyor is required to state the present Condition of the

Decks	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Sound when seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirketting	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears	Counter <u>"</u>	Cables <u>"</u>
Waterways	Plank and Treenails <u>Good</u>	Anchors No. of <u>"</u>
Hatchway Comings	(Outside to the Water's Edge.)	Standing & Running Rigging <u>Good</u>
Breasthooks	Rudder <u>"</u>	<u>Yellow Metal patched</u>
	Windlass <u>"</u>	

General Observations and Opinion, At the present time caused from Copper over all  
 as required by the Instructions, appears in all respects in good condition to continue  
a Classed

Committee Minute 16<sup>th</sup> May 1843

Character assigned 10 A 1

*[Signature]*

No. 255 Survey held at London Date May 10<sup>th</sup> 1843  
 on the S<sup>r</sup> Nancy Laps Master J Love  
 Tonnage 114 Built at Dartmouth When built 1839  
 By whom built \_\_\_\_\_ Owners Love & Co  
 Port belonging to Dartmouth Destined Voyage Gibraltar  
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 293 Port of Dartmouth, Lon 7/14/2 Classed 12A1  
Lic. 48/4.

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound when seen</u>	Pumps
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c.
Spirketting <u>Good</u>	Wales <u>"</u>	Sails
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>Good</u>
Waterways <u>"</u>	Plank and Treenails <u>Good</u>	Anchors No. of <u>of sufficient</u>
Hatchway Comings <u>"</u>	(Outside to the Water's Edge.)	Standing & Running Rigging
Breasthooks <u>"</u>	Rudder <u>"</u>	Copper
	Windlass <u>"</u>	

General Observations and Opinion, This vessel is not belge bottd & the Nelson only  
 as required by the Instructions, bottd every alternate floor timber & the ceiling  
generally badly shifted  
am of opinion she is not entitled to a higher  
Class than 10 A 1 See Dartmouth No 557

Committee Minute 16<sup>th</sup> May 1843

Character assigned \_\_\_\_\_

*[Signatures and notes]*  
 but cannot all at present  
 I have not all the cases  
 before me, but the  
 others present