

ANNUAL SURVEYS.

9798

No. 326 Survey held at London Date May 16 1843
 on the Bl. Eliza Kellick Master E. Davis
 Tonnage 200 Built at Liverpool When built 1830
 By whom built Wilson Owners H. Kellick
 Port belonging to Liverpool Destined Voyage St. Domingo
 If Surveyed Afloat or in Dry Dock Newham Dock

Original Survey, No. 3031, 4487 Port of Liverpool May 1842 Classed *A.1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

Good when seen
Good & very firm
Good and efficient
12 ft 3 in

General Observations and Opinion, *Caulked to trace and sheathed with yellow paper as required by the Instructions, to 12.3 - Nothing. Bottom very firm and good - In my opinion this is fit for the conveyance of dry and perishable cargoes to and from all parts of the world eligible to remain as classed *A.1 with the asterisk*

Committee Minute 13th June 1843

Character assigned A.1 *George Bayley*

No. 110 Survey held at London Date May 17 1843
 on the St. Marchion of Butte Master H. John
 Tonnage 196 Built at Newport When built 1839
 By whom built Barth Owners Bird & Co.
 Port belonging to Cardiff Destined Voyage
 If Surveyed Afloat or in Dry Dock Newport Dock

Original Survey, No. 1141 Port of London Sept 1842 Classed 12A1
Newport, 18th. 412, Lon 9112.

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

Good
Good
Good & efficient
See See
Good
a little wrinkled on the Larboard side

General Observations and Opinion, *Repairing copper - presents throughout a fine & substantial appearance & is in my opinion eligible to remain as classed 12A1*

Committee Minute 13th June 1843

Character assigned 12A1 *George Bayley*

