

REPORT of SURVEY for REPAIRS.

No. 740 Survey held at London Date 17th 19th 20th 24th June 1843
 on the B^{re} Matilda Luckie Master Mowro
 Tonnage 275 Built at Sunderland When built 1834
 By whom built _____ Owners Luckie & Co
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock in Donsow Dock

Original Survey, No. 1014, 2421, Dated _____ Classed 10 A 1
 Port London 3123, 3569, 5932, 6732, 7636, 7656, 8307, 9715,

REPAIRS at this time she has had new Plank Sheers & Her Ketting on both sides forward and seven new wrought-iron stanchions on the larboard side & eight on the starboard side - new Paintstrakes to quarter deck on both sides of last endia. Leak with new bolts & binding all slack bolts in hanging knees renewed - The wing transom & first transom being defective have been removed with several of the buttock Planks and properly replaced the iron locators have been taken down and refitted & bolted - There has been also a new false stern post with new rudder bands and new rudder trunk fitted to her - the vessel has been Caulked all over and the bottom & coppered on Borradaile's

Present Condition of the					
Decks	<u>Good</u>	Transoms	<u>New wing & 1st transom</u>	Windlass	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Where seen Good</u>	Capstan	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Good</u>	Pumps	<u>Do</u>
Spirketting	<u>New forward</u>	Wales	<u>Do</u>	Masts, Yards, &c.	<u>Sufficient</u>
Plank Sheers	<u>Do</u>	Counter	<u>Do</u>	Sails	<u>Do</u>
Waterways	<u>Do</u>	Plank & Treenails (Outside to the Water's Edge)	<u>Part new treenails</u>	Cables	<u>Do</u>
Hatchway Comings	<u>Do</u>	Rudder	<u>Main & 1st hoop Good</u>	Anchors	No. of <u>3 Bower & 1 Stream</u>
Breasthooks	<u>Do</u>	Copper	<u>New on felt June 1843</u>	Standing & Running Rigging	<u>Sufficient</u>

General Observations and Opinion,
 The above repair has been Carefully and Satisfactorily done - as she is in efficient & Sound Condition she may remain as Classed
Joseph H. Hatcher

The Amount of Fee.....£ 1 : - : - is received by me, J. Hatcher
 Committee's Minute 18th July 1843
 Character assigned 10 A 1 used permanently
 Lloyd's Register Foundation
 LON 615-0346