

# ANNUAL SURVEYS.

10,138

No. 24 Survey held at London Date Sept 30<sup>th</sup> 1843  
 on the Bk Ealing Grove Master Falconer  
 Tonnage 324 Built at Redbridge When built 1840  
 By whom built W Morris Owners Falconer  
 Port belonging to London Destined Voyage Dominica  
 If Surveyed Afloat or in Dry Dock Lincoln Dock

Original Survey, No. 9134 Port of London October 1842 Classed 12A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

*Good* *Good* *Good & efficient*

General Observations and Opinion, *Copper smooth & free from wrinkling excepting in*  
*as required by the Instructions, forebody - the sculptures of the shells additionally bolted - she*  
*is in my opinion eligible to remain as at present classed*

Committee Minute 17<sup>th</sup> October 1843 12A1 George Bayley  
 Character assigned 12A1 *LB*

No. 394 Survey held at London Date Sept 26<sup>th</sup> Oct 5 1843  
 on the Bk Lian Master Smith  
 Tonnage 388 Built at Newcastle When built 1840  
 By whom built  Owners Bertram  
 Port belonging to Newcastle Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Lincoln Dock

Original Survey, No. 10703 Port of London 1840 Classed 10A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

*Good* *Good* *Good* *Good* *Good* *3. 1. 2* *Good* *Good*

General Observations and Opinion, *Striped - 400 Treenails shifted in upper course and*  
*as required by the Instructions, a short piece of plank shifted (Timber good) Sheathed*  
*with Yellow Metal to the brail on paper - In my opinion*  
*she is eligible to remain as classed*

Committee Minute 17<sup>th</sup> October 1843 10A1 George Bayley  
 Character assigned 10A1 *Record Ym B*