

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 10686 Survey held at London Date March 1843
 on the By Dapper Master Judson
 Tonnage 219 Built at Hull When built 1827
 By whom built _____ Owners Judson
 Port belonging to London Destined Voyage Coastwise
 If Surveyed Afloat or in Dry Dock on the Ways

Original Survey, No. _____ Dated _____ Classed A, 1

Port of London

REPAIRS At the present time caulked from the keel to the gunwale

Present Condition of the

Decks	<u>Good</u>	Transoms	<u>Sound</u>	Windlass	_____
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame	<u>sound & heresies</u>	Capstan	_____
Lower Deck Beams & Fastenings	<u>"</u>	Topsides	<u>Good</u>	Pumps	_____
Spirkettling	<u>"</u>	Wales	<u>"</u>	Masts, Yards, &c.	_____
Plank Shears	<u>"</u>	Counter	<u>"</u>	Sails	<u>Not found</u>
Waterways	<u>"</u>	Plank and Treenails (Outside to the Water's Edge)	<u>"</u>	Cables	_____
Hatchway Comings	<u>"</u>	Rudder	<u>"</u>	Anchors No. of	_____
Breasthooks	<u>"</u>	_____	_____	Standing & Running Rigging	_____

General Observations and Opinion, I am of opinion is fit for the safe conveyance of
dry & perishable cargoes and may continue as classed

[Signature]

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18 _____

Character assigned _____



© 2019

Lloyd's Register
Foundation

LON 617 - 0216