

REPORT of SURVEY for REPAIRS.

10939

Change of Owners

Rec 21 Aug 44

No. 425 Survey held at London Date August 20 1844

on the Bk Winchester Master Milligan

Tonnage 336 Built at Sunderland When built 1837

By whom built Owners Buckles & Co

Port belonging to Lancaster Destined Voyage Port Adelaide

If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 9663 Classed 11A1

Port London

REPAIRS Caulked above the Copper - By Yell

Present Condition of the

| | | |
|-------------------------------|-------------------------------|----------------------------|
| Decks | Transoms | Windlass |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Capstan |
| Lower Deck Beams & Fastenings | Topsides | Pumps |
| Spirketting | Wales | Masts, Yards, &c. |
| Plank Shears | Counter | Sails |
| Waterways | Plank and Treenails | Cables |
| Hatchway Comings | (Outside to the Water's Edge) | Anchors No. of |
| Breasthooks | Rudder | Standing & Running Rigging |
| | Copper | |

General Observations and Opinion,

Is in a very sound & efficient state and appears in all respects eligible to retain her present class

The Amount of Fee.....£ 2 : - : - is received by me,

Committee's Minute 23rd August 1844

Character assigned 11A1



© 2019

Lloyd's Register Foundation

LON 617-0479