

ANNUAL SURVEYS.

11103

No. 165 Survey held at London Date Nov 16 1844
 on the Bg. Apicurus Master S. S. S. S.
 Tonnage 105 Built at Yarmouth When built 1830
 By whom built Owners Foster & Co
 Port belonging to London Destined Voyage Gambia
 If Surveyed Afloat or in Dry Dock on the ways

Last Survey, No. 9605 Port of London

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound & true</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Bows 2 Hedges</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Presents a very firm appearance and is in all
 as required by the Instructions, respects fit to retain her present class

Committee Minute 29th Nov 1844

Character assigned 12 A 1

No. 807 Survey held at London Date Nov 19 1844
 on the Schooner Arrow Master J. Goring
 Tonnage 176 Built at Yarmouth When built 1841
 By whom built Deasdale Owners Bell & Co
 Port belonging to Yarmouth Destined Voyage Yarmouth & Mediterranean
 If Surveyed Afloat or in Dry Dock on the ways

Last Survey, No. 571 Port of Yarmouth

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Good</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Bows 2 Hedges</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>much patched</u>

General Observations and Opinion, Bottom examined & Copper patched,
 as required by the Instructions, Is altogether in a very efficient state to continue
in her present class

Committee Minute 29th Nov 1844

Character assigned 12 A 1