

# REPORT of SURVEY for REPAIRS.

and Continuation

No. 132 Survey held at London Date 10<sup>th</sup> 11<sup>th</sup> 13<sup>th</sup> Oct 1845  
 on the Brig "Sabel & Lignes" Master Cummings  
 Tonnage 143 Built at Stockton When built 1841  
 By whom built \_\_\_\_\_ Owners J Saidler  
 Port belonging to Stockton Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock on Fountain Ways

Last Survey, No. 1184

Classed 4 A 1

Port Leith

REPAIRS

at Present Damage Sustained by Collision repaired  
 two new stern timbers and new stern plank and <sup>after</sup> piece of larboard sheerstrake - renewed - bolts  
 and hooding ends of bottom Caulked - The upper & lower  
 deck bolts and treenails driven out for survey and the  
 outside planks through which they pass the waterways  
 and beams where seen - The main timbers knee heads  
 breasthooks & transoms the floors & keelsons - planking outside  
 from the keel upwards the ceiling inside the frame and  
 inner surface of the outside planking where it has been  
 the deck & lower side sound & good and the sheer and  
 general form of ship unaltered

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>—</u>	Breasthooks and Stemson	<u>—</u>	Pumps	<u>—</u>
Comings	<u>—</u>	Transoms, Pointers, and Crutches	<u>—</u>	Boats	<u>—</u>
Upper Deck Beams & Fastenings	<u>—</u>	Timbers of the Frame <u>where seen good for Clap</u>	<u>Good</u>	Masts, Yards, &c.	<u>Sufficient</u>
Lower Deck Beams & Fastenings	<u>—</u>	Keelsons	<u>—</u>	Sails	<u>—</u>
Plank sheers	<u>—</u>	Clamps and Shelves	<u>Good</u>	Anchors No. of	<u>—</u>
Sheerstrakes	<u>—</u>	Ceiling	<u>—</u>	Cables	<u>—</u>
Topsides	<u>—</u>	Rudder	<u>—</u>	Hawsers and Warps	<u>—</u>
Wales	<u>—</u>	Copper	<u>None</u>	Standing & Running Rigging	<u>—</u>
Plank (Bottom) and Counter	<u>—</u>				

General Observations and Opinion,

This Vessel appears in efficient Condition  
 and may be continued on the first Clap  
 as long as the Rules admit say from  
 1845. 1 A 1

The Amount of Fee.....£ 2 : — : — is received by me, J H Hickey

Certificate (if required) : :

Committee's Minute 17<sup>th</sup> Oct 1845

Character assigned Class A 1 for 1 year

Mr Denham Clerk & Smith

J H Hickey

© 2019

Lloyd's Register  
 Foundation

LON619-0446