

REPORT of SURVEY for REPAIRS.

Change of Property

12052

No. 489 Survey held at London Date Feb 1895 1845
 on the Sea View Master Messrs Matthias
 Tonnage 90 Built at Bones When built 1831
 By whom built — Owners R Bennet & Son
 Port belonging to London Destined Voyage Home
 If Surveyed Afloat or in Dry Dock on the ways

Last Survey, No. 11070

Classed 8 F. 1

Port London

REPAIRS

*at the present time from being on shore
 Caulked from the keel up additional bolts in the
 keel & gripe a few planks shifted in the deck*

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good when seen</u>	Windlass and Capstan <u>Good sufficient</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>do</u>	Pumps <u>do do</u>
Comings <u>do</u>	Transoms, Pointers, and Ceatches <u>Good</u>	Boats <u>do do</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>Good when seen</u>	Masts, Yards, &c. <u>do do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>do do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do do</u>
Wales <u>do</u>	Copper <u>none</u>	Standing & Running Rigging <u>do do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

*She is now in an efficient condition fit for
 the conveyance of dry & perishable cargoes
 and may run as is classed*

The Amount of Fee.....£ : 10 : — is received by me, H

Certificate (if required) : 5 : — H

Committee's Minute 11th Nov 18 95

Character assigned 4

R Bennet & Son

[Signature]

Lloyd's Register
 Foundation

LON620-0064