

ANNUAL SURVEYS.

No. 34 Survey held at Sidon Date Apr. 3rd 1845
 on the ship St Vincent Master S. Young
 Tonnage 497 Built at Sidon When built 1829
 By whom built By the Government Owners British Govt
 Port belonging to Sidon Destined Voyage Greece
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 20453 Port of Sidon Restored 1844 Classed A, 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>for condition</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, Sc. <u>overhauled</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Bore & 1 Star 2 Hoops</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>plated with No. 1045</u>

General Observations and Opinion, Ship appears to be in good condition, and all respects to a very efficient state to retain her present shape
 as required by the Instructions, Rest & 1

Committee Minute 14th Nov 1845

Character assigned Rest & 1

No. 72 Survey held at Sidon Date Dec 3rd 1845
 on the ship St Vincent Master Silk
 Tonnage 438 Built at Sidon When built 1804
 By whom built By the Government Owners British Govt
 Port belonging to Sidon Destined Voyage Batavia
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 11877 Port of Sidon Classed A, 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>for condition</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, Sc. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>well found</u>
Waterways <u>"</u>	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Ship appears to be in good condition, and all respects to a very efficient state to retain her present shape
 as required by the Instructions, Rest & 1

Committee Minute 14th Nov 1845

Character assigned Rest & 1