

REPORT of SURVEY for REPAIRS.

Change of Names 12192

No. 932 Survey held at London Date 11 January 1845
 on the Ship. Mount Stuart of London Holton
 Tonnage 641 Built at Wimbor When built 1826
 By whom built — Owners J Somers
 Port belonging to London Destined Voyage New South Wales
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 9670

Classed F. 1 expiring

Port London

REPAIRS

Waterways to now caulked

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Some</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Kelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topside <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>do</u>	Standing & Running Rigging <u>particular</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

A strong substantial Ship in the most efficient condition for the conveyance of any and practicable cargo to from all parts of the World and may with advantage be employed

The Amount of Fee.....£ 3 : : is received by me.

Certificate (if required) : 10 : -

Committee's Minute

Character assigned

H. J. Somers

Lloyd's Register
Foundation

1220-020107