

# REPORT of SURVEY for REPAIRS.

*Change of Owners*

No. 285 Survey held at London Date 15<sup>th</sup> 17 April 1846  
 on the Sch. "Eliza Ann" Master \_\_\_\_\_  
 Tonnage 137 Built at New Brunswick When built 1816  
 By whom built \_\_\_\_\_ Owners W. Dowell  
 Port belonging to London Destined Voyage Coal trade  
 If Surveyed Afloat or in Dry Dock in Hawks Dock

Last Survey, No. 860 Classed N.A.

Port Plymouth  
 REPAIRS at present Copper stripped off and bottom Caulked  
and not replaced bottom left single  
written notice sent to owners to open at bilges in  
accordance with Sect 63. but she has sailed  
without doing so -

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>None</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

## General Observations and Opinion,

*Under the Circumstances should be marked*  
*Not opened*


*S. H. Ritchie*

The Amount of Fee.....£ \_\_\_\_\_ is received by me,

Certificate (if required) : :

Committee's Minute 28th April 1846

Character assigned Efficient Character  
Not opened



© 2019

Lloyd's Register  
 Foundation

LON 621-0008