

REPORT of SURVEY for REPAIRS.

12580

No. 573 Survey held at London Date 28th May 3rd June 1846
 on the Brig "Ann" Master John Popham
 Tonnage 165 Built at Chester When built 1815
 whom built _____ Owners Cram & Co.
 Port belonging to Liverpool Destined Voyage Liverpool &
 If Surveyed Afloat or in Dry Dock on Wet's Ways

Last Survey, No. 6564-7612 Classed *A. 1

Port Liverpool

REPAIRS at present make upper Cowlers topsides and Sheerstrakes
 Caulked. 5 Roughten timbers shifted abreast of fore
 rigging on larboard side with new studs & bulwarks -
 Notice sent on 28th May to comply with Sect. 60 and
 to repair the topsides and sheerstrakes which are
 much decayed - but the Master declined complying
 with my recommendation until the vessel reaches
 Liverpool for which port she is about to sail -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	<u>Y. Metal, good</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

until this vessel is repaired she is not
 entitled to be classed higher than E 1

J. H. Ritchie

The Amount of Fee £ : : is received by me,

Certificate (if required) : :

Committee's Minute 9th June 1846
 Character assigned See Liverpool No. 7612

Anti Lloyd's

© 2019 Lloyd's Register Foundation