

REPORT of SURVEY for REPAIRS.

12750

No. 37 Survey held at London Date 14th Aug^r 1846
 on the Brig "Ames" Master _____
 Tonnage 197 Built at Nova Scotia When built 1841
 By whom built _____ Owners E Stabb
 Port belonging to St John Newfound Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Duke Shore Dock

Last Survey, No. 10261 Classed 4 A.1
 Port London Expunged

REPAIRS

at present bottom Caulked the lower breast
 hook ^{being} decayed has been removed and a new
 one of sound second hand ~~one of~~ English oak
 fitted this Vessel has now been opened for
 government survey and the timbers found generally
 sound - Written notice was sent to the Owner
 to open the Vessel in Compliance with Section
 63. but which he declined doing.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Corrings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Under the above Circumstances this
 Vessel should be marked "Not Opened,"

A. H. H. H.

The Amount of Fee.....£ : : is received by me,

Certificate (if required) : :

Committee's Minute 21st Aug^r 1846

Character assigned

Not Opened



© 2019

Lloyd's Register
 Foundation

LON 621-0302