

# REPORT of SURVEY for REPAIRS.

12857

No. 294 Survey held at London Date April 29<sup>th</sup> to May 5<sup>th</sup> 1846  
 on the Bk Henry Tanner Master Burgess  
 Tonnage 388 Built at Wardland When built 1834  
 By whom built \_\_\_\_\_ Owners Thomson & Co  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Afloat, West India Dock

Last Survey, No. 11410 Continued 1844 Classed 3A1  
 Port London

REPAIRS All the bolts in the iron lodging knees to the side beams renewed and some of the throat bolts in the hanging knees shifted - new marringing and a general overhaul in the rigging -

Present Condition of the		
Decks	<u>Good</u>	Treenails <u>good</u>
Waterways	"	Breasthooks and Stems <u>"</u>
Comings	"	Transoms, Pointers, and Crutches <u>good</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame <u>sound &amp; true</u>
Lower Deck Beams & Fastenings	"	Keelsons <u>good</u>
Planksheers	"	Clamps and Shells <u>"</u>
Sheerstrakes	"	Ceiling <u>"</u>
Topsides	"	Rudder <u>"</u>
Wales	"	<u>Copper 4/11 1845</u>
Plank (Bottom) and Counter	"	
		Windlass and Capstan <u>good</u>
		Pumps <u>"</u>
		Boats <u>"</u>
		Masts, Yards, &c. <u>"</u>
		Sails <u>well found</u>
		Anchors No. of <u>3 Bower 1 Stn 2 Hedges</u>
		Cables <u>well</u>
		Hawsers and Warps <u>"</u>
		Standing & Running Rigging <u>good</u>

General Observations and Opinion, We are of opinion this vessel may retain her present class, being in an efficient state in the hull & stores

*[Signature]*

The Amount of Fee ..... £ \_\_\_\_\_ is received by me,

Certificate (if required) : :

Committee's Minute 1 Oct. 1846

Character assigned Class 3 A  
Special 11.1.0 AA  
5/10/46