

# REPORT of SURVEY for REPAIRS.

12884

No. 168 Survey held at London Date Oct 6<sup>th</sup> to Oct 15<sup>th</sup> 1846  
 on the Gibraltar B? Master Goodbourn  
 Tonnage 257 Built at Sunderland When built 1842  
 By whom built \_\_\_\_\_ Owners Forman  
 Port belonging to London Destined Voyage St Vincent  
 If Surveyed Afloat or in Dry Dock Townson's Slip & West India Dock

Last Survey, No. 11060 Classed 7 A 1

Port London

REPAIRS Has had two broken hanging knees taken out and two pair of iron hanging knee riders put in, New ceiling repaired & repainted & fixed up

## Present Condition of the

|  |   |   |
|--|---|---|
| Decks <u>good</u>                                    | Treenails <u>good so far as seen</u>          | Windlass and Capstan <u>in good order</u>         |
| Waterways <u>"</u>                                   | Breasthooks and Stemson <u>good</u>           | Pumps <u>" " "</u>                                |
| Comings <u>"</u>                                     | Transoms, Pointers, and Crutches <u>"</u>     | Boats <u>Long and jelly</u>                       |
| Upper Deck Beams & Fastenings <u>good &amp; firm</u> | Timbers of the Frame <u>good when seen</u>    | Masts, Yards, &c. <u>apparently in good order</u> |
| Lower Deck Beams & Fastenings <u>"</u>               | Keelsons <u>good</u>                          | Sails <u>2 suit</u>                               |
| Planksheers <u>good</u>                              | Clamps and Shelves <u>"</u>                   | Anchors No. of <u>3 B. 15. 16.</u>                |
| Sheerstrakes <u>"</u>                                | Ceiling <u>rep<sup>d</sup> &amp; fixed up</u> | Cables <u>2 Bower chains</u>                      |
| Topsides <u>"</u>                                    | Rudder <u>2<sup>nd</sup></u>                  | Hawsers and Warps <u>in use of a stream</u>       |
| Wales <u>"</u>                                       | Copper <u>1/2 in now rep<sup>d</sup></u>      | Standing & Running Rigging <u>in good order</u>   |

## General Observations and Opinion,

This ship has had her bottom examined and is considered in good & efficient condition & remains as at present classed

Aug. Bruce

The Amount of Fee.....£..... is received by me,

Certificate (if required).....

Committee's Minute 16 Oct 1846

Character assigned 7 A 1

Special attendance £1-1-0



© 2019

Lloyd's Register  
Foundation

LON 621-0441