

# REPORT of SURVEY for REPAIRS.

13191

No. 27 Survey held at London Date Feb<sup>ry</sup> 5<sup>th</sup> to 13<sup>th</sup> 1847  
 on the Barque "Acasta" Master B Robertson  
 Tonnage 305 Built at Aberdeen When built 1845  
 By whom built \_\_\_\_\_ Owners B Moir  
 Port belonging to Aberdeen Destined Voyage Singapore  
 If Surveyed Afloat or in Dry Dock In Hackwood's Dry Dock

Last Survey, No. 1133 Classed 9 A 1  
 Port Aberdeen 45

REPAIRS done at the present time from damage sustained in her passage from South America to London.

The Yellow Metal Sheathing stripped off and renewed upon Felt; Caulked from upper edge of Wales to keel, hung in Shous; Sheeps of Keel additionally Bolted, the Chafed parts of Keel and Bottom Plank, dubbed over, and the Bulwarks repaired.

## Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	} good	Breasthooks and Stemson	} good when seen	Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} d <sup>o</sup> when seen	Timbers of the Frame	} d <sup>o</sup>	Masts, Yards, &c.	} In good order and sufficient
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves	d <sup>o</sup>	Anchors No. of	
Sheerstrakes	d <sup>o</sup>	Ceiling	d <sup>o</sup>	Cables	
Topsides	d <sup>o</sup>	Rudder	d <sup>o</sup>	Hawsers and Warps	
Wales	d <sup>o</sup>	Copper	Yellow Metal on Felt now new	Standing & Running Rigging	
Plank (Bottom) and Counter	d <sup>o</sup>				

## General Observations and Opinion,

We are of opinion that this Ship is now in good condition fit to retain her Class A 1

The Amount of Fee.....£ \_\_\_\_\_ is received by me,

Certificate (if required) \_\_\_\_\_

Committee's Minute

Character assigned

Special Report on damage £35.0



Lloyd's Register  
Foundation  
LON622-0269