

Change of Owners REPORT of SURVEY for REPAIRS.

No. 593 Survey held at London Date May 4 1847
 on the By "Smiley" Master P. Henderson
 Tonnage 187 Built at Sunderland When built 1832
 By whom built - Owners J. J. Smith and Macdonald
 Port belonging to London Destined Voyage Archangel Repsford
 If Surveyed Afloat or in Dry Dock Swidings OK

Last Survey, No. 12264

Classed A. 1

Port Sunderland

REPAIRS

Over hauled & altered to find a leak

Present Condition of the

Decks

Good

Treenails

Good

Windlass and Capstan

efficient

Waterways

do

Breasthooks and Steason

do

Pumps

do

Comings

do

Transoms, Pointers, and Crutches

do

Boats

do

Upper Deck Beams & Fastenings

Secure

Timbers of the Frame

good & true

Masts, Yards, &c.

do

Lower Deck Beams & Fastenings

do

Kelsons

Good

Sails

do

Plankbeers

Good

Clamps and Shells

do

Anchors No. of

do

Sheerstrakes

do

Ceiling

do

Cables

do

Topsides

do

Rudder

do

Hawsers and Warps

do

Wales

do

Copper

Standing & Running Rigging

do

Plank (Bottom) and Counter

General Observations and Opinion,

It is in an efficient condition fit for the
Conveyance of any kind of merchandise to & from
all parts of the world and may remain as
Clipped

The Amount of Fee.....£ / : is received by me,

Certificate (if required)

Committee's Minute

4th June 1847

Character assigned

A. 1