

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 338 Survey held at London Date Oct 11th 1847
 on the B^{re} Liverpool Master Mr Whitty
 Tonnage 557 Built at Halifax When built 1835
 By whom built _____ Owners W Price & Co
 Port belonging to Quebec Destined Voyage _____
 If Surveyed Afloat or in Dry Dock In Mess^r Fletcher & Co^s Dry Dock

Last Survey, No. 12241

Classed 5 A 1
S 46.4 yrs 46

Port London

REPAIRS of damage by being on Shore. Reported by the Master to be done at Quebec in July, August, Sept & October 1846 which repairs he attended, and as far as may be seen appear to be efficiently performed

The whole of Main Keel, Stern Post, lower Piece of Stem, all the Floors new of American Oak, also fifteen First Futtock, each side, the whole Flat of Bottom up to about First Futtock heads ^{new} and from thence to Wales Sheathed with Fir ^{1 1/2} thick upon Felt.

Inside. New Ceiling in Flat of Hold of Elm, the whole of Main and Riding Keelsons of Oak, all the Hold Beams except one, and several Laying knees new

Now done. The Chafed parts of Main Keel dressed off and ^{repaired at Port and} the Bottom Caulked. Iron hanging knees and Rides wedged up.

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stems	Pumps
Comings } <u>good</u>	Transoms, Pointers, and Crutches } <u>good when seen</u>	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>In good order</u>
Lower Deck Beams & Fastenings } <u>all right</u>	Keelsons <u>new</u> <u>all</u>	Sails } <u>and sufficient</u>
Planksheers	Clamps and Shells <u>all</u>	Anchors No. of
Sheerstrakes <u>all</u>	Ceiling <u>all</u>	Cables
Topsides <u>all</u>	Rudder <u>all</u>	Hawsers and Warps
Wales <u>all</u>	<u>all</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>all</u>		

General Observations and Opinion, Wood Sheathed from Wales to 1st Futtock Heads upon Felt

This Barque now appears to be in good condition eligible to remain as Classed A 1

The Amount of Fee.....£ 3 : is received by me. W J Martin

Certificate (if required) : :

Committee's Minute 12 Nov 1847

Character assigned 1st Class



© 2019

Lloyd's Register
Foundation

LON 624-0016