

REPORT of SURVEY for ~~REPAIRS~~.

14288

No. 65 Survey held at London Date 20 May 1848
 on the By "General Belgrano" Master Farido
 Tonnage 350 Built at Misla When built 1834
 By whom built — Owners Lambi
 Port belonging to Pinas Agus Destined Voyage Sailed for Cadiz 5/5/48
 If Surveyed Afloat or in Dry Dock J. Katherin D. K. M. L. & P. Constructions

Last Survey, No. 12009 Clussed A. 1.
 Port London 46

REPAIRS

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchor No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

She is very loose in her deck fastenings and is otherwise out of condition notice was given to put in some screws &c and she has sailed without doing any repairs. I am of opinion

The Amount of Fee.....£ : : is received by me, *She is not in fit*

Certificate (if required) : : *condition to remain as*

Committee's Minute 23 May 1848

Character assigned General Character

Special £2 2.0



© 2019
 Lloyd's Register
 Foundation
 LON 624-0478