

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 739 Survey held at LONDON Date 21st 24th June 1848
 on the Brig "Marian" Master _____
 Tonnage 212 Built at Yarmouth When built 1840
 By whom built _____ Owners Beil & Sons
 Port belonging to LONDON Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock in Gun Dock

Last Survey, No. 1775 Classified 12 A 1

REPAIRS at present bottom stripped Caulked from Keel to gun wale and bottom sheathed with Yellow Metal on felt. Wale topside & sheerstrakes Scraped & repayed and found sound & good

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stenson	Pumps	
Comings	Transoms, Pointers, and Catches	Boats	<u>new long boat</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.	<u>different</u>
Lower Deck Beams & Fastenings	Keelsons	Sails	<u>about 1 new</u>
Planksheers	Clamps and Shelves	Anchors	No. of <u>3</u>
Sheerstrakes	Ceiling	Cables	<u>different</u>
Topsides	Rudder	Hawsers and Warps	<u>different</u>
Wales	Cooper	Standing & Running Rigging	<u>good</u>
Plank (Bottom) and Counter	<u>Y Metal on felt</u>		

General Observations and Opinion,

This Vessel is in efficient Condition and may remain as Classed

The Amount of Fee £ 1 : 0 : 0 is received by me,

Certificate (if required) : 10 : 0 : 0

Committee's Minute 30th June 1848

Character assigned 12 A 1



© 2019 Lloyd's Register Foundation