

# ANNUAL SURVEYS.

14588

No. <sup>715</sup> on the Brig "Fortitude" Survey held at London Date 18<sup>th</sup> Aug<sup>r</sup> 1848  
 Tonnage 519 Built at Scarbro' Master J. Chestman  
 By whom built \_\_\_\_\_ Owners Tindalls  
 Port belonging to Scarbro' Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock in Snooks Dock

Last Survey, No. 3006 Port of London Classed 12 A 1

The present Condition of the		
Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Ym</u> When put on <u>repaired</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

Good

Good

Well found and sufficient

General Observations and Opinion,  
*This Vessel is in perfect order and may leave as ordered*  
 Committee Minute 1<sup>st</sup> Sept 1848  
 Character assigned 12 A 1  
*J. H. Ritchie*

Certificate (if required)

No. <sup>471</sup> on the Brig "Amy" Survey held at London Date 19<sup>th</sup> Aug<sup>r</sup> 1848  
 Tonnage 232 Built at Topsham Master \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners Cole Ho  
 Port belonging to Exeter Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock in Youngs Dock

Last Survey, No. 715 Port of Cork Classed 12 A 1

The present Condition of the		
Decks <u>Caulked Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>New fore mast beam</u>
Lower Deck Beams & Fastenings	Keelsons	Sails <u>Sufficient</u>
Planksheers	Clamps and Shelves	Anchors No. of <u>5</u>
Sheerstrakes	Ceiling	Cables <u>5</u>
Topsides	Rudder	Hawsers and Warps <u>5</u>
Wales <u>Caulked</u>	Copper <u>of metal</u> When put on <u>new</u>	Standing & Running Rigging <u>repaired</u>
Plank (Bottom) and Counter		

General Observations and Opinion,  
*at present bottom stripped of bottom & Copper sheathing Caulked to the upper part of Wales bottom sheathing replaced on felt and bottom sheathed with yellow metal on paper new fore mast shipped.*  
 Committee Minute 1<sup>st</sup> Sept 1848  
 Character assigned 12 A 1  
*J. H. Ritchie*

Lloyd's Register Foundation