

REPORT of SURVEY for REPAIRS.

No. 357 Survey held at London Date Oct 2 1848
 on the Ship "London" Master [Signature]
 Tonnage 612 Built at London When built 1833
 By whom built Weymans Owners Shuttleworth
 Port belonging to London Destined Voyage Manxas
 If Surveyed Afloat or in Dry Dock Weymans Dock

Last Survey, No. 12851 Port London Classed 12 Rest 16 A1

REPAIRS At the present time Shipped Caulked from the Keel up
House pipes refitted false Keel made good madder overhauled
for part of the decks around the bolts caulked generally
examined and resheathed with felt & yellow paint
and new for mast.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Seam</u>	Timbers of the Frame <u>Good when new</u>	Masts, Yards, &c. <u>4 1/2 ft</u> <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shells <u>do</u>	Anchors No. of <u>2 D S W</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Vales <u>do</u>	Copper <u>do</u> When put on <u>1840</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

Ship in an efficient condition and may remain
as shipped

Amount of Fee.....£..... is received by me.

Special..... : : :

Certificate (if required) : : :

Date 10th Nov 1848

By [Signature]



© 2019

Lloyd's Register
Foundation

LON 625-0407