

REPORT of SURVEY for REPAIRS.

No. 93 Survey held at London Date Jan 20th 1849
 on the Sc "Lady Rebekah" Master X
 Tonnage 57 Built at Worke When built 1836
 By whom built _____ Owners Blythe & Co.
 Port belonging to Colchester Destined Voyage St Michael
 If Surveyed Afloat or in Dry Dock In Fountain Slipway

Last Survey, No. 13426 Port London Classed 10 A 1
Cont 46 3 47

REPAIRS

at the present time of damage sustained by being ran into by a Brig while lying at anchor off Dover, more particulars in Special Report.

Knee of Head, Rails &c new, Windlass repaired, a new Bowsprit, Flat of Deck in Bows repaired, the foremost Beam of Deck new, sundry Rigging of Bowsprit and Fore Mast new and the Fore part of Vessel above the Yellow Metal Caulked.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good when seen</u>	Pumps
Comings } <u>good</u>	Transoms, Pointers, and Crutches } <u>good when seen</u>	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order and sufficient</u>
Lower Deck Beams & Fastenings <u>all as new</u>	Keelsons <u>not seen</u>	Sails
Plank sheers	Clamps and Shelves <u>d^o</u>	Anchors No. of
Sheerstrakes <u>d^o</u>	Ceiling <u>d^o</u>	Cables
Topsides <u>d^o</u>	Rudder <u>d^o</u>	Hawsers and Warps
Wales <u>d^o</u>	Copper Metal When put on <u>d^o 45</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>d^o</u>		

General Observations and Opinion,

This Schooner now appears to be in good condition eligible to remain as Classed A 1

The Amount of Fee.....£ : 10 : - is received by me, J. A. Martin

Special..... 2 : 2 : -

Certificate (if required) : 5 : -

Committee's Minute 2nd Feb 1849

Character assigned Cont 3 A 1

Special Report &c 2-2-0
 to Damage



© 2019

Lloyd's Register
 Foundation

LON 626 0102