

# REPORT of SURVEY for REPAIRS.

No. 71 Survey held at London Date 12 to 24 Jan 1849  
 on the By "General Balgarnie" Master J. Farido  
 Tonnage 298 Built at Bristol When built 1834  
 By whom built — Owners Lt. Santa Maria & Co  
 Port belonging to Buenos Ayres Destined Voyage Buenos Ayres  
 If Surveyed Afloat or in Dry Dock Wp' Gromy' St

Last Survey, No. 14288 Port London Classed expended  
 REPAIRS now for recapping now 14288

11 new fitting him bars. The sheathing strokes in the lower  
 decks ceiling now fitted with thick planks through  
 fastened, also two strokes in the hold 150 feet of new wales  
 on the starboard side, the bottom additionally bolted with  
 yellow metal and the wales and upperworks with iron bolts  
 8 pairs of iron hanging knees in the hold, and also  
 8 pairs in the <sup>decks</sup> twist, to the Deck Beams, pointers and  
 hooks rebolted caulked from the keel up over the sheathing  
 with yellow metal upon feet,

## Present Condition of the

Decks <u>Good</u>	Treenails <u>bolts</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>—</u>	Breasthooks and Stenson <u>altered</u>	Pumps <u>do</u>
Comings <u>—</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>Strong</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>—</u>	Anchors No. of <u>3 B 15 lb</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>—</u>	Cables <u>do</u>
Topsides <u>—</u>	Rudder <u>—</u>	Hawsers and Warps <u>do</u>
Wales <u>—</u>	Copper <u>Ym</u> When put on <u>May</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>—</u>		

## General Observations and Opinion,

It now in an efficient condition fit  
 for the conveyance of any and perishable cargo and  
 may be recapped.

The Amount of Fee.....£ 1 : : is received by me,

Special..... 2 : 2 : -

Certificate (if required) : 10 : -

Committee's Minute 6th July 1849

Character assigned Good

Special L2. 2



© 2019

Lloyd's Register  
Foundation

LON 626 0110