

# REPORT of SURVEY for REPAIRS.

No. 116 Survey held at London Date Feb 10 17 6 184 9  
 on the M Margaret Master Clark  
 Tonnage 436 Built at New Brunswick When built 1839  
 By whom built 556 Owners W. H. Allen  
 Port belonging to London Destined Voyage New York  
 If Surveyed Afloat or in Dry Dock Weymouth OK

Last Survey, No. 13261 Port London Classed 4 B. 1 S. 4. 1. 1

## REPAIRS

Present time opened in conformity with the Society's Rules  
 Section three timbers on each side in the after body has defects  
 three others slightly so - fillings choakes and posts are put and  
 the ceiling wrought when the timbers had been cut down  
 2 pairs of Iron Bolts wrought to over to compensate for the  
 deficiency in the frame In the fore body 3 timbers on the London  
 side defective cut out and wrought to long choaks and 2  
 fillings. The ceiling new in the fore shafts and one pair of  
 long Iron Bolts and two long chins wrought to compensate  
 new anchor stock piece in main keelson, and a new stay for top  
 upper works Cautious - clamping pieces in holes

## Present Condition of the

Decks <u>wooden</u>	Treenails <u>good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>good</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c. <u>put new</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>good</u>	Sails <u>2 Sails</u>
Planksheers <u>good</u>	Clamps and Shells <u>do</u>	Anchors No. of <u>3 1 1 1 1</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>new</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>put</u> When put on <u>1849</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>good</u>		

## General Observations and Opinion,

Is in good and efficient condition fit for the  
 conveyance of dry and perishable cargoes and may be classed  
 A. 1 and marked S. 5 3 years -

The Amount of Fee.....£ 3 : : is received by me.

Special..... 2 : 2 : -

Certificate (if required) : : -

Committee's Minute 20th March 1849

Character assigned A. 1 S. 5 3



© 2019

Lloyd's Register  
Foundation

LON 626-0218