

**REPORT of SURVEY for REPAIRS.**

No. 395 Survey held at LONDON Date 28<sup>th</sup> May 1849  
 on the Bark Alverton Master A. Buckland  
 Tonnage 343 Built at Sunderland When built 1844  
 By whom built \_\_\_\_\_ Owners A. Towse  
 Port belonging to LONDON Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock in Kings Dock

Last Survey, No. 14210 Port LONDON Classed 10 A 1

## REPAIRS

at present docked and yellow metal repaired  
 New Main Piece of Rudder fitted - New fore topmast  
 and Sparker boom and new quarter boat and  
 quarter davits furnished -

When sheathed with yellow metal in 1848 the iron  
 bolt under it were removed of yellow metal  
 the mark "over St. I B" should therefore be  
 expunged from the Register Book

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder <u>New main</u>	Hawsers and Warps
Wales	Copper <u>14<sup>th</sup> May</u> When put on <u>1848</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

## General Observations and Opinion,

This Vessel is in efficient Condition  
 and may remain as classed

The Amount of Fee.....£ 2 : : is received by me,

Special..... 2 : 2 : -

Certificate (if required) : :

Committee's Minute 14<sup>th</sup> Aug 1849

Character assigned 10 A 1

Special Damage £2.2



© 2019  
 Lloyd's Register  
 Foundation