

REPORT of SURVEY for REPAIRS.

Change of owner 15/83

No. 208 Survey held at London Date Dec 18 18 49
 on the "Agnes" Master J. A. Finlay
 Tonnage 203 Built at Dumbarton When built 1825
 By whom built _____ Owners Leake
 Port belonging to London Destined Voyage Open
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 15318 Port London Classed A.1

REPAIRS

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 B/S 1/2</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper — When put on —	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

She is in good and efficient condition
and may remain as Classed
Good

The Amount of Fee.....£ 1 : — : — is received by me,

Special..... : — : —

Certificate (if required) : 10 : —

Committee's Minute 20th Jan'y 1850

Character assigned A.1



© 2019

Lloyd's Register
Foundation

LON 627-0416